CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Highway Materials Testing Laboratory)
An ISO 9001: 2015 Certified Company
NABL Accredited As Per ISO/IEC : 17025:2005 Laboratory

JAS-ANZ
ISO 9001:2000 CERTIFIED

Name of Work :Pot hole filling in ward No.12, Dasarahalli Division, BBMP, Bangalore

Name of Client	:	**Executive Engineer,** Dasarahalli Division , BBMP, Bangalore.
Contractor/Agency	:	**Technical Manager, KRIDL,** Bangalore.
Total Cost	:	Rs.5.54Lakhs
Date of Inspection	:	26.09.2015
Status of Bill	:	1st & Final Bill
In the Presence of	:	(a) **Assitant Engineer** W. No.12, BBMP, Bangalore.
	:	(b) **Mr. Vinay Kumar B,** Engineer M/s Civil Quality Consultants & Engineers, Bangalore.

PMC Compliance Report

Sl.No	Description of the Item		Comments / observations
1.	Earthwork excavation by manual means in ordinary soil involving		Work done up to the billed quantity and Quality is satisfactory
2	Providing, laying, spreading and compacting graded stones aggregate to…..		Work done up to the billed quantity and Quality is satisfactory
3	Tack coat-Providing and laying tack coat with…..	:	Work done up to the billed quantity and Quality is satisfactory
4	KSRRB 3000 Filling pot-holes and patch repairs with…..	:	Work done up to the billed quantity and Quality is satisfactory
5	Disposal of debris to the final place of disposal with all lead and…..	:	Work done up to the billed quantity and Quality is satisfactory

For CIVIL QUALITY CONSULTANTS & ENGINEERS

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Authorised Signatory

Authorised Signatory

Scanned by CamScanner